



## TRASFORMATORI IN FERRITE

### EF 16



20x18  
A=15




H=14  
B=3.81

16.7x11  
A=7.75

H=17  
B=3.81

22x15  
A=8.89  
H=22  
B=3.81

### EF 19



20x17  
A=12.5

H=16  
B=5  
vista lato pin

20x18  
A=15

H=14  
B=2.5  
PAG. 50

20x20  
A=17.5  
H=18.5  
B=5